



# Tesla Model Y Long Range Awd

VIN NO LRWYGCEK0MC063255  
Registration Number EC95519



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



-

-

2

69463 km

-

-

2021-09-09

Norway

## Inspection Report Summary


Customer	BCA Norway	Report Number	P20241126112358
Inspection Date / Place	2024-11-26 / BCA Bilauksjon AS	Cosmetic Grade	4


## Vehicle Summary

Vehicle Identification Number	LRWYGCEK0MC063255	VAT Type	Margin
Vehicle Condition	Runner	Gearbox Type	Automatic
Fuel Type	Battery Electric Vehicle	Number of Keys	2
Colour	Dark Grey	Engine Size (cc)	0
Engine Size	0.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Leather
Charging Cables	Type 1 + Type 2	WLTP CO2 Emissions	

## Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			







## Equipment

---

Digital Radio

Sunroof

Adaptive Cruisecontrol

Satellite navigation

Tow ball

## Wheels & Tyres

---

### Mounted Tires

Tyre / Wheel Type

Summer

//R / 3.8 mm

//R / 3.2 mm

//R / 2.4 mm

//R / 2.4 mm

### Unmounted Tires

Tyre / Wheel Type

Winter


//R / 7.6 mm

//R / 7.9 mm

//R / 7.1 mm

//R / 7.2 mm

## Cosmetic Damage




Component	Damage	Comments
1 Set of 4 Winter Wheels	Paint / Scratch / Scuff	
2 Tailgate	Paint / Defective Workmanship	
3 Bumper / Back	Paint / Scratch / Scuff	
4 Bumper / Front	Bodywork / Dent / Deformation	
5 Rim / Front Right	Out of Bodywork / Scratch	
6 Rim / Back Right	Out of Bodywork / Scratch	
7 Rim / Back Left	Out of Bodywork / Scratch	
8 Fender / Back Right	Paint / Scratch / Scuff	
9 Bumper / Back	Paint / Scratch / Scuff	
10 Tire / Front Left	Tire	


11	Tire / Front Right	Tire
12	Tire / Back Right	Tire
13	Tire / Back Left	Tire
14	Bumper / Front	Bodywork / Dent / Deformation
15	Bumper / Front	Bodywork / Dent / Deformation
16	License Plate / Front	Out of Bodywork / Deformation




1. Set of 4 Winter Wheels  
Paint / Scratch / Scuff -



2. Tailgate  
Paint / Defective Workmanship -



3. Bumper / Back  
Paint / Scratch / Scuff -



4. Bumper / Front  
Bodywork / Dent / Deformation -



5. Rim / Front Right  
Out of Bodywork / Scratch -



6. Rim / Back Right  
Out of Bodywork / Scratch -






7. Rim / Back Left  
Out of Bodywork / Scratch -



8. Fender / Back Right  
Paint / Scratch / Scuff -



9. Bumper / Back  
Paint / Scratch / Scuff -




10. Tire / Front Left  
Tire -




11. Tire / Front Right  
Tire -



12. Tire / Back Right  
Tire -



13. Tire / Back Left  
Tire -



14. Bumper / Front  
Bodywork / Dent / Deformation -



15. Bumper / Front  
Bodywork / Dent / Deformation -



16. License Plate / Front  
Out of Bodywork / Deformation -

## Mechanical Condition

OBD Test	Not Tested	Electric Mirror Movement	Ok
Electric Window Movement	Ok	Driving Experience	Good
Electrical System	Good	Engine	Good
Signlight Illuminate	Ok	Wiper Arm Movement and Washers	Ok
Headlights Illiminate	Ok	Control of High Beam	Ok
Sidelights Illiminate	Ok	Foglights Illiminate	Ok
Indicators Illiminate	Ok	Brake Lights Illuminate	Ok
Battery State of Health	Ok	Engine Oil Level	Not Applicable
Brake Fluid Level	Ok	Coolant Level	Ok
Power Steering Fluid Level	Ok	Oil / Coolant Contamination	Not Applicable
Brake Disc / Front - Left	Ok	Brake Disc / Front - right	Ok
Brake Disc / Rear - Right	Ok	Brake Disc / Rear - Left	Ok

## Test Drive Inspection

Adaptive Cruise Control	Not Tested	Aircon Recieves Power (ex Gassing)	Ok
Aux Belt / Pulley Noise	Not Applicable	Brake Efficiency Test	Ok
Central Locking (ex Key Fob)	Ok	Comments	control_answer_kjører på korden
Convertible / Sunroof Electrics	Not Applicable	Engine Running	Ok
Engine Smoking	Not Applicable	Exhaust (no Leaks & Secure)	Not Applicable
1st & Reserve Drive / Clutch Slip Test (static)	Not Applicable	Hand Brake Test	Ok
Horn	Ok	Max Speed Under Test	80
Sat Navn Recieves Power (ex Functionality)	Ok	Starts	Ok
Statis Gear Selection (engine Running)	Not Applicable	Steering Noise	Ok
Suspension Ride Height (ex - air Susp)	Ok	Temp Outside Under Test	7
Vehicle Condition (dirty/clean)	Clean	Weather Condition Under Test	Rainy